

# Release Notes

---

## Public Release

### Version 1.0.16

Features	<ul style="list-style-type: none"> <li>N/A</li> </ul>
Bug Fixes	<ul style="list-style-type: none"> <li>Increased stability when switching inputs while using Marantz SR7013, Anthem MRX-720, and Denon X6500H &amp; S740H AVRs.</li> </ul>
Known Issues	<ul style="list-style-type: none"> <li>Some video loss and flickering may occur with Integra DRX-5.2, DRX-4.2, and DRX-7.1 AVRs.</li> </ul>

## Previous Releases

### Version 1.0.15

Features	<ul style="list-style-type: none"> <li>N/A</li> </ul>
Bug Fixes	<ul style="list-style-type: none"> <li>Fixed an issue with Mode 4 (5V Lock), which sets the +5V and the HPD signal of the transmitter and receiver to high. In certain cases, when the display was turned off, the HPD signal would go low, which is what Mode 4 is designed to prevent.</li> </ul>
Known Issues	<ul style="list-style-type: none"> <li>N/A</li> </ul>

### Version 1.0.14

Features	<ul style="list-style-type: none"> <li>N/A</li> </ul>
Bug Fixes	<ul style="list-style-type: none"> <li>Fixed an issue where Dolby Vision content would display the incorrect color space when connected to a Sony X900F display.</li> <li>Video sync issue addressed: In rare cases, repeated input switching would result in audio, but no video, when the extender was connected to an AV switch.</li> </ul>
Known Issues	<ul style="list-style-type: none"> <li>N/A</li> </ul>

### Version 1.0.12

Features	<ul style="list-style-type: none"> <li>N/A</li> </ul>
Bug Fixes	<ul style="list-style-type: none"> <li>Increased compatibility with non-Atlona extenders.</li> </ul>
Known Issues	<ul style="list-style-type: none"> <li>N/A</li> </ul>

### Version 1.0.11

Features	<ul style="list-style-type: none"> <li>N/A</li> </ul>
Bug Fixes	<ul style="list-style-type: none"> <li>Fixed an issue where the DirecTV C61K-700 would detect the sink device as non-4K device when the extender kit is rebooted, or if a loss of signal occurred.</li> <li>Fixed an issue where “green banding” would be displayed on HDMI video, with certain sources such as DirecTV HR54-700 (firmware release 0x1104).</li> <li>Fixed an issue where HDCP “snow” would occur during channel changes when using the DirecTV C61K-700.</li> </ul>
Known Issues	<ul style="list-style-type: none"> <li>N/A</li> </ul>

**Version 1.0.07**

Features	<ul style="list-style-type: none"><li>• N/A</li></ul>
Bug Fixes	<ul style="list-style-type: none"><li>• Resolved an issue which resulted in a “snowy” picture or signal loss, when using a DirecTV 4K source.</li><li>• Resolved incompatibility issue with Dolby Vision 4K @ 30 Hz on several types of displays.</li></ul>
Known Issues	<ul style="list-style-type: none"><li>• N/A</li></ul>

**Version 1**

<ul style="list-style-type: none"><li>• Factory Firmware</li></ul>
--