

Release Notes

Public Release

Version 1.1.44

Features	<ul style="list-style-type: none">When the unit is connected to a DVI it will now hold a 2Channel audio block, so audio can be passed from source to speakers.
Bug Fixes	<ul style="list-style-type: none">LG TVs no longer cause the unit to crash when they are connected to the AT-HDR-M2C.
Known Issues	<ul style="list-style-type: none">None

Previous Releases

Version 1.1.41

Features	<ul style="list-style-type: none">Added host name support allowing modification of the host name of the unit.Added host name information to the System sta command.
Bug Fixes	<ul style="list-style-type: none">Resolved a lock-up issue, experienced on 1.1.40, which could occur during the firmware update process.Fixed an issue where the volume would randomly change after a hard power cycle.Fixed an issue where Spotify audio streams, routed over the Analog Audio output, would stop passing audio.

Version 1.1.22

Features	<ul style="list-style-type: none">Recessed button now supports factory reset. Hold for more than 20 seconds to reset the unit.Added ability to copy sink EDID and apply it to the HDMI input. Available options:<ul style="list-style-type: none">a. Default HDMI OUTb. Default HDMI PCM2
Bug Fixes	<ul style="list-style-type: none">Stability improvements to Web server and Telnet interface.Fixed issue with incorrect audio channel being reported in the web interface: 7.1-channel was being reported as 5.1-channel.Fixed issue on analog and digital outputs that previously caused audio to be heard when audio was muted.Resolved issue with Dolby® Vision™ content pass-through that resulted in an incorrect color space.Black frame insertion is removed if set to standby mode.Fixed HDMI AV drop-follow input switching when connected to AVRs (several models).
Known Issues	<ul style="list-style-type: none">Analog audio and TOSLINK output audio is approximately 100 milliseconds ahead of HDMI output, when using certain test generators.

Release Notes

Version 1.1.01

Features	<ul style="list-style-type: none">• Hostname information is now displayed as HDR-M2C-xxxxxx, where xxxxxx are the last six digits of the MAC address.
Bug Fixes	<ul style="list-style-type: none">• Fixed an HDCP issue involving MacBook Air on AT-HDR-M2C reboot.• Fixed an issue where the preferred timing could not be set, unless an HDMI display was connected to the output.
Known Issues	<ul style="list-style-type: none">• N/A

Version 1

- Factory Firmware